

1/6




FIG. 1

2/6

EXAMPLES OF "RESOURCES" THAT CAN BE CHECKED OUT

1. TOOL CONTROLS (EACH CHECKED OUT INDIVIDUALLY)
 - TOP DRIVES
 - SCR CONTROLS
 - DRAWWORKS CONTROLS
2. ELECTRONIC DRILLING SYSTEM
 - RPM, WOB, TRQ, ΔP
 - PUMP STROKES, DRAWWORKS
3. PRESSURE MANAGEMENT SYSTEM
 - PUMP STROKES
 - CHOKE CONTROL
4. SOLID CONTROL
 - PUMP STROKES
 - SHAKER CONTROL
 - CENTRIFUGE CONTROL
 - CHEMICAL ADDITIVE CONTROL
5. TRIPPING MANAGEMENT SYSTEM
 - DRAWWORKS, IRON ROUGHNECK
 - RPM
 - SWAB/SURGE LIMITS
6. DOWNHOLE TOOL CONTROL
 - PUMP STROKES
 - RPM
 - SEQUENCING SCHEMES

FIG. 2

3/6




FIG. 3

4/6

E-DRILLER		ED to Tracer communication failed		1:47:29 07/20/03	
Hookload 0.0 Klbs		Stand Pipe Pressure 0 Psi		ELECTRONIC DRILLER	
ELECTRONIC DRILLER MODE SELECT					
WOB	ROP	DELTA PSI	TORQUE	AUTO-DRILLING CONTROL	Ready
0.0	0	0	0	OFF	Comms OK
50	500	500	600	ON	Alarm
40	400	400	500		
30	300	300	400		
20	200	200	300		
10	100	100	200		
0	0	0	100		
Setpoint	Setpoint	Setpoint	Setpoint		
0.0	0	0	0		
BLOCK CONTROL				Block Position	
				0.0 FT	
				Hi Setpoint	
				0.0	
				Lo Setpoint	
				0.0	
				Set Hi/Lo Setpoint	
				Calibrate Block Ht	
				Screen Controls Enabled	
				Coolant Override	
				System Override	
				Parked	
				ESD	
				Configuration	
				Monitor	
				Alarms	
				Auto Driller Monitor	

FIG. 4

USER AUTHORIZATION SCREEN				
MODIFY?	ORGANIZATION	USER	AUTHORIZATION	RESOURCES
<input type="checkbox"/>	CONTRACTOR 1	USER1	PASSWORD	DOWNHOLE TOOL CONTROL
<input type="checkbox"/>	CONTRACTOR 1	USER2	KEY-ACCESS	ELECTRONIC DRILLER
<input type="checkbox"/>	CONTRACTOR2	USER3	SUPERVISED	TOP DRIVE & PIPE HANDLER
<input type="checkbox"/>	CONTRACTOR3	USER4	PASSWORD W/MANUAL ACKNOWLEDGE	SWAB/SURGE CONTROL

FIG. 5

6/6




FIG. 6




FIG. 7